

PRECISION DIMENSIONING EXERCISE #3

DIRECTIONS:

Complete a THREE-VIEW drawing of a SPLINE COLLAR and dimension completely
Use the specifications on the handout or download provided by your instructor

NOTE: The example drawing is at HALF scale. (**Double** your dimensions)

Geometric Dimensioning and Tolerancing (Madsen) page 302

